

McPHERSON & THOM (ALTA) LTD.
428 MORRIS ROAD N.E.
CALGARY, ALBERTA T2A 2P2
PHONE 273-8676

DRAWDOWN TEST
~ 2 yrs AFTER WELL DRILLED -

Water Level Measurements (field)

Well No.
Location of project SPRINGBANK
Status PUMPING (pumping or observation well)
Well Owner: ARTISAN HOMES
Well location: Lsd. or 1/4 Sec. 13, Tp. 24, R. 3, Mer. W. 5
R =
Date OCT 7 1981
Measured by: P. M. NORMAN
Page 1
(distance from pumping well in feet and direction)

Date	Time hrs. & mins.	Elapsed time in mins.	Recovery		Depth to water in feet METER	Draw- down in feet	Q l/gpm	Remarks (i.e. pumping rate, water temp., static level, etc.)
			t	1/t				
10/7		0			17.50		20	
		1			17.70		20	
		2			17.70		20	
		3			17.70		20	
		4			17.705		20	
		5			17.705		20	
		6			17.705		20	
		7			17.71		20	
		8			17.71		20	
		9			17.71		20	
		10			17.71		20	
		15			17.72		20	
		20			17.72		20	
		25			17.72		20	
		30			17.725		20	
		40			17.73		20	
		50			17.74		20	
		60			17.74		20	
		75			17.745		20	
		90			17.745		20	
		105			17.75		20	
		120			17.75		20	
		150			17.75		20	
		180			17.75		20	
		181			17.55			WATER SAMPLE TAKEN
		182			17.55			START RECOVERY
		183			17.55			

10:30 AM - 10:45 AM

